

Remediation Progress Rate Report

Bangladesh Safety Agreement

Data As of 30 June 2026

Overview

This report presents the current progress at factories inspected by the RMG Sustainability Council (RSC) and covered under the Bangladesh Safety Agreement (BSA). It showcases overall remediation progress as well as progress on specific fire, electrical, structural, and boiler safety items with high life-saving value.

Starting in January 2026, this report is produced quarterly by the RSC, following a decision by the Accord Steering Committee to revise the methodology for calculating factory remediation progress rates and to provide a breakdown of progress on specific, high-impact safety findings.

Factory Coverage under the Bangladesh Safety Agreement

• No. of Factories:	1,773
• Active:	1,680
• Inactive Responsible:	60
• Pending Closure:	33

Current Remediation Progress

(Fire & Life Safety, Electrical Safety & Structural Safety)

Initial Findings	95,912
RSC Verified as Corrected	81%
Factory Reported as Pending Verification	87%
New Findings	60,413
RSC Verified as Corrected	81%
Factory Reported as Pending Verification	89%
Total Findings	156,325
RSC Verified as Corrected	81%
Factory Reported as Pending Verification	88%

Specific Remediation Items

Fire Safety	RSC Verified as Corrected	69%
	Factory Reported as Pending Verification	83%

	Number of Factories Concerned	Number of Findings	Progress Rate (Initial + New Findings)	
 Means of Egress	1,713	25,559	RSC Verified as Corrected	75%
			Factory Reported as Pending Verification	89%
 Fire Alarm & Detection System (FADS)	1,701	3,324	RSC Verified as Corrected	55%
			Factory Reported as Pending Verification	66%
 Fire Suppression System (SUPS)	1,401	2,896	RSC Verified as Corrected	52%
			Factory Reported as Pending Verification	63%

Electrical Safety	RSC Verified as Corrected	92%
	Factory Reported as Pending Verification	95%

	Number of Factories Concerned	Number of Findings	Progress Rate (Initial + New Findings)	
 Electrical Single Line Diagram (SLD)	1,667	2,799	RSC Verified as Corrected	73%
			Factory Reported as Pending Verification	81%

Structural Safety	RSC Verified as Corrected	74%
	Factory Reported as Pending Verification	78%

	Number of Factories Concerned	Number of Findings	Progress Rate (Initial + New Findings)	
 (Detailed) Engineering Assessment (D)EA	1,716	15,998	RSC Verified as Corrected	73%
			Factory Reported as Pending Verification	77%
 Structural Retrofitting	1,696	12,428	RSC Verified as Corrected	74%
			Factory Reported as Pending Verification	79%

Current Remediation Progress

(Boiler Safety)

No. of Factories with Boilers	1,387
No. of Boilers Covered	4,007

	Number of Factories Inspected	Number of Boilers Inspected	Number of Findings	Progress Rate (Initial + New Findings)	
Boilers¹	1,302	3,128	23,871	RSC Verified as Corrected	13%
				Factory Reported as Pending Verification ²	73%
Boilers with Critical Findings	372	641	N/A	RSC Verified as Corrected	51%
				Factory Reported as Pending Verification	0%
				Boiler Temporarily Shut Down for Remediation	36%
				Boilers Permanently Shut Down	13%

Notes:

¹ RSC covers pressure vessels that generate steam from water at pressures **above 1 bar** , regardless of their size.

² RSC verification of completion started for boilers with Critical Findings. Regular FUIs started in **June-2025**

Technical Glossary

This glossary provides definitions of key technical terms and phrases used throughout the report. The glossary includes both individual terms (e.g., abbreviations, system names) and phrases that are specific to the inspections and remediation program implemented by the RSC under the Bangladesh Safety Agreement.

Term / Phrase	Definition
CAP Terms	
Factory Reported as Pending Verification	The percentage of items "Pending Verification" includes items that have been verified as corrected and items that are ready for RSC verification.
Initial Findings	Safety hazards identified during the first inspection of the factory.
New Findings	Safety hazards identified during a follow-up inspection after the initial inspection.
Total Findings	The combined number of safety findings, including Initial and New Findings.
Safety Hazards	
Boilers with Critical Findings	Serious conditions or defects that can compromise its safe operation. These issues may require immediate attention and corrective action before the boiler can continue operating.
(Detailed) Engineering Assessment (D)EA	A comprehensive evaluation of a building's structural components to identify risks, ensure compliance with safety standards, and recommend corrective actions for safe operation. Without (D)EA acceptance, associated remediation items cannot commence.
Electrical Single Line Diagram (SLD)	A simplified representation of an electrical system, showing the main components and their connections using single lines and standardised symbols. An accurate SLD can help identify issues in the system that could lead to electrical hazards, such as short-circuits, high temperatures and fires.
Factory Reported as Pending Verification	The percentage of items "Pending Verification" includes items that have been verified as corrected and items that are ready for RSC verification.
Fire Alarm & Detection System (FADS)	A system designed to detect fire or smoke and alert occupants through visual and audible signals, enabling prompt evacuation and emergency response.
Fire Suppression System (SUPS)	An engineered system is designed to control or extinguish fires automatically or manually by releasing substances such as water, foam, gas, or chemicals to suppress flames and prevent the spread of fire.
Means of Egress	A safe and unobstructed path for occupants to exit a building or structure during an emergency.
Structural Retrofitting	The process of strengthening or modifying an existing structure to improve safety, durability, and performance. Typically undertaken to enhance resistance to earthquakes, wind loads, or other stresses not considered in the original design.